April 8, 2019

Discontinued Service Parts

Effective April 8, 2019, residential and light duty commercial **ICON 1.0** gas valve kits have been discontinued and replaced with the **New ICON 2.0** gas valve kits. Orders will be accepted for ICON 1.0 through Tuesday April 9, 2019 for any remaining available inventory. As a reference, please see the table below for replacement part number information.

The new ICON 2.0 service kits are fully compatible as a direct replacement for the original ICON gas valve. These service kits include a pilot assembly, making them a perfect solution for field service of residential and light duty commercial gas water heaters—both atmospheric and direct vent, manufactured since FVIR integration in July of 2003.

Discontinued ICON 1.0 Gas Valve



New ICON 2.0 Gas Valve



Description	**Discontinued** ICON 1.0 Replaced by New ICON 2.0		
	Discontinued Part #		**Replacement Part #**
RG1- Nat Gas	239-47463-01	Replaced By	415-52907-01
RG2- Nat Gas	239-47463-02	Replaced By	415-52907-02
RG275, M2XR75, RG2100 & MI100 - NAT	239-48275-05	Replaced By	415-53361-03
RG1 - LP	239-47465-01	Replaced By	415-52909-01
RG2-LP	239-47465-02	Replaced By	415-52909-02
RG275, M2XR75, RG2100 & MI100 - LP	239-48275-06	Replaced By	415-53361-04
URG2 – Nat Gas	239-48863-01	Replaced By	415-52915-01
URG275 & URG2100 – Nat Gas	239-49841-02	Replaced By	415-52913-02
LG2 – Nat Gas –180°F	239-47464-02	Replaced By	415-52908-02
LG2 – LP – 180°F	239-47466-02	Replaced By	415-52910-02
ULG250 – Nat Gas – 180°F	239-49861-01	Replaced By	415-52916-01
ULG275 & ULG2100 – Nat Gas – 180°F	239-49843-01	Replaced By	415-52914-01
Universal Service Kits – 30-65 Gallon – NAT	239-47851-00	Replaced By	415-53359-00
Universal Service Kits – 30-65 Gallon – LP	239-47856-00	Replaced By	415-53360-00

If you have any questions, or require additional information, please contact the Parts Department via email at Parts@bradfordwhite.com or by calling 1-800-532-4020.